


William Roberts Vintage

Industrial Pipe Clothing Rack with Side Shelves

Assembly Directions

You will need 2 people to correctly assemble the Clothing Rack. The following tool will be needed:



Pipe Wrench

You will also need cloth to help prevent these tools from damaging pipe surfaces. You will need two strong people to hold and tighten pipe fittings.

1. Lay Pipe (A) with elbow fittings on floor.
2. Attach both (B) pipes with T fittings into elbow fittings on each side of the (A) pipe. Tighten (B) pipes at the top where (B) pipes screw into (A) pipe. Make sure both T fittings on the bottom of (B) pipes are facing each other. **All pipes should be flat on floor.**
3. Undo Union (if necessary) (sometimes ship with union together) and Attach both (C) pipes with union to each T fitting. Make both tight with pipe wrench. **Make sure all pipes are lying flat on the floor.** Adjust if needed
4. Screw Union Fitting together and tighten. Now you should have a square / rectangle shape.
5. Rotate so the bottom of the T fittings on (B) pipes are pointing upward. Screw legs (D) into T fitting on (B) pipes. Make sure legs are tight and 90 degrees from base. Adjust as needed.
6. Screw side shelves into (B) pipes.
7. Level the rack by tightening or loosening flange fittings attached to legs (D).

